MARS MD.

2- ANNA

10-

Cornelius Brocksby- John Shaw House #10 State Circle Annapolis Anne Arundel County Maryland

PHOTOGRAPH

WRITTEN HISTORICAL AND DESCRIPTIVE DATA



Historic American Buildings Survey National Park Service Department of the Interior Washinton, D.C. 20013

BROOKSBY-SHAW HOUSE Annapolis, Anne Arundel County, Maryland

Date of erection: 1720-1725 and later

Present condition: Altered in 1922 for Elks Lodge

Builder: Cornelius Brooksby and Anne Gough

Description:

One and a half stories; brick; gambrel roof; "stagger stairs" in attic; kitchen in basement; "captain's walk"; addition by Cornelius Brooksby, Jr., in 1745. Other alterations and additions to interior by Sowell Lang before 1751. East end sddition by John Shaw, 1784.

Additional data:

Now used as BPOE Lodge Hall.

Erected 1720-21 by Cornelius Brooksby, completed by Anne Gough his widow 1725. Laddition on Church St. by Cornelius Brooksby Jr. and his father-in-law Thomas Gough prior to 1745. Interior improved and steps to trap door in roof by Sowell Long betw. 1745 and 1751. Last addition by Elks 1922.

Ground allotted to Mrs. Margaret Mersier widow of John. Cornelius Brooksby bought ground after his marriage to Anne Shahan on March 23, 1719 and built a 2 story house with 2 living rooms and basement with a single room upstairs. Cornelius Brooksby will probated Kuly 19, 1723 left house to son John and butcher shop to daughter Mary. Cornelius (John) Brooksby sold his interest to his sister and brother-in-law Sowell Long June 7, 1745. David Long son of Sowell and Mary Long transferred the property to John Shaw May 24, 1784. John Shaw's will probated March 9, 1829, left the house to his son George.

Information furnished by A. Guy Miller, Sect. Elk's Lodge, Annapolis 1934

Prepared by Delos H. Smith 1940

Brooksby-Shaw House (John Shaw House)
21 State Circle (Current Information)'
Annapolis
Anne Arundel County
Maryland

HABS MD, 2-ANNA, 10-

MD-250

HABS No.

Addendum to
Cornelius Brooksby-John Shaw House
#10 State Circle (As originally recorded)
Annapolis
Anne Arundel County
Maryland

PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

Historic American Buildings Survey
National Park Service
Department of the Interior
Washington, D.C. 20240

Form 10-920 (June 1983)

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

HABS No. MD-250 Brooksby-Shaw House Data Sheet (2)

ARCHITECTURAL DATA FORM

STATE	COUNTY		TOWN OR VICINITY	
Maryland	Anne Arundel		Annapolis	
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME) Brooksby-Shaw House			HABS NO. MD-250	
SECONDARY OR COMMON NAMES OF S	STRUCTURE		<u> </u>	i
John Shaw House COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES)				
21 State Circle	TION FOR RURAL	311E3)		
DATE OF CONSTRUCTION (INCLUDE SOURCE) ARCHITECT(S) (ARCHITECT(S) (INC.	LUDE SOURCE)	
1719-1721				
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE) An 18th century house ,largely altered, in excellent condition and with several interesting original features.				
STYLE (IF APPROPRIATE) Colonial				
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS)				
Brick, laid in English bond, painted. Facade is stuccoed and marked to simulate stone.				
SHAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE)				
One and ½ stories above high basement;55' long; originally rectangular in plan.				
EXTERIOR FEATURES OF NOTE Originally a small porch in front of entrance door, with a gable roof, a low elliptical arch and slender columns, approached from the side by a wooden stair The present porch incorporates this motif. A large brick chimney exists at each gable end, projecting from facade. Main entrance has wide wooden architrave 7 glazed transom. The roof is a gambrel; there is a molded wooden cornice in front, now obscured by the porch. There are three hipped dormers on the front of the house.				
INTERIOR FEATURES OF NOTE The stair leading to the attic is unusually steep, with treads staggered (alternating between the right and left halves of the stair).				
MAJOR ALTERATIONS AND ADDITIONS WITH DATES				
1745 "Captain's Walk" added; 1784 east end addition; 1922 Converted to Elk's Club. For further information see Data Page one.				
PRESENT CONDITION AND USE The house now serves as the offices of the Maryland Historical Trust.				
OTHER INFORMATION AS APPROPRIA	TE			
SOURCES OF INFORMATION (INCLUDIA Data at the Library of Report submitted to I	of Congress.			
COMPILER, AFFILIATION Eleni S:	ilverman, HABS A	Architectural His	storian	DATE July 1983